

March 24, 2011

Asbestos and Pb (Lead) Survey UCSB Carrillo/Santa Cruz Boilers Bldgs. 562/548

The University of California Santa Barbara (UCSB), Design and Construction Services (DC&S) has compiled this report to disclose existing knowledge of asbestos and Pb (Lead) containing building components located at Buildings 562 and 548 on the UCSB Campus.

Asbestos Sampling

Table 1.0 Asbestos Laboratory Reports lists the reports attached by Report Number, Date, Laboratory, Analysis Type, and Comments.

Table 1.0 - Asbestos Laboratory Reports

Report #	Report Date	Laboratory	Analysis Type	Comments
B143829	01/07/2011	Forensic Analytical	PLM EPA Method 600/R-93-116	Various samples on the boilers and related equipment in Bldg. 548.
B142810	12/08/2010	Forensic Analytical	PLM EPA Method 600/R-93-116	Samples 01-06 are various samples in the boiler room of Bldg. 562.

Lead Paint Sampling Results


Table 2.0 Pb (Lead) Laboratory Reports lists the reports attached by Report Number, Date, Laboratory, Analysis Type, and Comments.

Table 2.0 – Pb (Lead) Laboratory Reports

Report #	Report Date	Laboratory	Analysis Type	Comments
M115353	12/09/2010	Forensic Analytical	TTLIC Metal Analysis Flame AA	Various Samples in the boiler room of Bldg. 562.

UCSB's industrial wastewater permit¹ local limit for lead is 1.040 mg/l. The California Code of Regulations, Title 22 classifies waste containing more than 50 ppm lead as hazardous² without further waste characterization. If you have any question regarding this report please contact me at 805-451-1918 or gene.horstin@dcs.ucsb.edu

Sincerely,



Digitally signed by Gene Horstin
DN: cn=Gene Horstin, ou=DCS, ou=UCSB,
ou=Design and Construction,
email=gene.horstin@dcs.ucsb.edu
Reason: I am the author of this
document
Date: 2011.03.28 13:31:04 -0700

Gene Horstin

University of California Santa Barbara

Asbestos and Pb Clerk of the Works

Asbestos Abatement Project Designer Cert# PD39-11

Asbestos Inspector & Management Planner Cert# BIMP91-11

Asbestos Contractor & Supervisor Cert# CS182-11

CDPH Lead Inspector/Assessor ID# 20134

¹Industrial Wastewater Discharge Permit Number IV-413, Part I, Wastewater Discharge Limitations and Monitoring Requirements – Local Limits

²TITLE 22. Social Security, Division 4.5. Environmental Health Standards for the Management of Hazardous Waste, Chapter 11. Identification and Listing of Hazardous Waste, Article 3. Characteristics of Hazardous Waste, §66261.24, Characteristic of Toxicity



Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

U.C. Santa Barbara
Project Manager
Design and Construction Svcs
Building 370
Santa Barbara, CA 93106

Client ID: 5151
Report Number: B143829
Date Received: 01/07/11
Date Analyzed: 01/10/11
Date Printed: 01/10/11
First Reported: 01/10/11

Job ID/Site: Santa Cruz Dorm Boiler Replacement - Bldg 548, Boiler Room

FALI Job ID: 5151-6556

Date(s) Collected: 01/05/2011

Total Samples Submitted: 16

Total Samples Analyzed: 16

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
20110105-548-PLM-1	11067268						
Layer: White Plaster			ND				
Layer: Paint			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
20110105-548-PLM-2	11067269						
Layer: White Plaster			ND				
Layer: Paint			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
20110105-548-PLM-3	11067270						
Layer: White Plaster			ND				
Layer: Paint			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
20110105-548-PLM-4	11067271						
Layer: Tan Semi-Fibrous Material			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (5 %)							
20110105-548-PLM-5	11067272						
Layer: Tan Semi-Fibrous Material			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (5 %)							
20110105-548-PLM-6	11067273						
Layer: Tan Semi-Fibrous Material			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (5 %)							
20110105-548-PLM-7	11067274						
Layer: Orange Foam			ND				
Layer: Paint			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					

Client Name: U.C. Santa Barbara

Report Number: B143829

Date Printed: 01/10/11

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
20110105-548-PLM-8	11067275						
Layer: Grey Non-Fibrous Material			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
20110105-548-PLM-9	11067276						
Layer: Grey Cementitious Material			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
20110105-548-PLM-10	11067277						
Layer: White Joint Compound			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
20110105-548-PLM-11	11067278						
Layer: White Joint Compound			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
20110105-548-PLM-12	11067279						
Layer: White Joint Compound			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
20110105-548-PLM-13	11067280						
Layer: Grey Semi-Fibrous Material			ND				
Layer: Paint			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (10 %) Fibrous Glass (30 %)							
20110105-548-PLM-14	11067281						
Layer: Grey Semi-Fibrous Material			ND				
Layer: Paint			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (10 %) Fibrous Glass (30 %)							
20110105-548-PLM-15	11067282						
Layer: Grey Semi-Fibrous Material			ND				
Layer: Paint			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (10 %) Fibrous Glass (30 %)							
20110105-548-PLM-16	11067283						
Layer: Grey Semi-Fibrous Material			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (10 %) Fibrous Glass (30 %)							

Client Name: U.C. Santa Barbara

Report Number: B143829

Date Printed: 01/10/11

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
-----------	------------	---------------	------------------	---------------	------------------	---------------	------------------



James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by Forensic Analytical Laboratories Inc. (FALI) at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by FALI to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by FALI. The client is solely responsible for the use and interpretation of test results and reports requested from FALI. Forensic Analytical Laboratories Inc. is not able to assess the degree of hazard resulting from materials analyzed. FALI reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.

University of California, Santa Barbara
 Environmental Health and Safety - Client # 5151
 Asbestos and Lead Program - Contact J. Ripley 805-893-7984 jerome.ripley@dcs.ucsb.edu

Bulk Sample Log
 Asbestos

Project: Santa Cruz Dorm Boiler Replacement

Date: 01/05/2011

W.O.#: 292-62

Sampler Name: G. Horstin

Building Name/Number: Bldg. 548 Boiler Room

Sample Analysis

Turn Around

PLM	12 HR	24 HR	Other
Lab Instructions:	Due Date: 01/10/11		

Sample No.	Material(s)	HID No.	Location
20110105-548-PLM-01	White plaster.		Bldg. 548, boiler room, ceiling, on north/south beam.
20110105-548-PLM-02	White plaster.		Bldg. 548, boiler room, ceiling, on east/west beam.
20110105-548-PLM-03	White plaster.		Bldg. 548, boiler room, ceiling, on east/west beam.
20110105-548-PLM-04	Block insulation		Bldg. 548, boiler room, on inside of Raypak boiler #2.
20110105-548-PLM-05	Block insulation.		Bldg. 548, boiler room, on inside of Raypak boiler #1.
20110105-548-PLM-06	Block insulation.		Bldg. 548, boiler room, on inside of Raypak boiler #1.
20110105-548-PLM-07	Firestopping.		Bldg. 548, boiler room, on ceiling, around pipe south of door.
20110105-548-PLM-08	Grey caulking.		Bldg. 548, boiler room, around door frame.
20110105-548-PLM-09	Black mastic.		Bldg. 548, boiler room, south wall, above switch boxes.
20110105-548-PLM-10	Joint compound.		Bldg 548, boiler room, on west wall, west of tanks.
20110105-548-PLM-11	Joint compound.		Bldg. 548, boiler room, on west wall, west of tanks.
20110105-548-PLM-12	Joint compound.		Bldg. 548, boiler room, on west wall, west of tanks.
20110105-548-PLM-13	Grey insulation.		Bldg. 548, boiler room, on tank #2 at south end of room.
20110105-548-PLM-14	Grey insulation.		Bldg. 548, boiler room, on tank #1 at south end of room.
20110105-548-PLM-15	Grey insulation.		Bldg. 548, boiler room, on tank #2 at south end of room.
20110105-548-PLM-16	Grey insulation. (down to metal tank)		Bldg. 548, boiler room, on tank #2 at south end of room.

Betty Feely 1030
 1/7/11

University of California, Santa Barbara
Environmental Health and Safety - Client # 5151
Asbestos and Lead Program - Contact J. Ripley 805-893-7984 jerome.ripley@dcs.ucsb.edu

Bulk Sample Log
Asbestos

Chain of Custody

Relinquished by Name: G. Horstin Company: UCSB

Date/Time: 1/7/11

I hereby agree to these terms
of the contract, and
I understand that
I am responsible for
the accuracy of the
information provided
herein and the safety of the
samples.

Received by Name: Betty Feda Company: FASI

Date/Time: 1/7/11

1030am



Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

U.C. Santa Barbara
Project Manager
Design and Construction Svcs
Building 370
Santa Barbara, CA 93106

Client ID: 5151
Report Number: B142810
Date Received: 12/07/10
Date Analyzed: 12/08/10
Date Printed: 12/08/10
First Reported: 12/08/10

Job ID/Site: Santa Rosa/Carrillo Dining Boiler Replacement, Bldgs 527 & 562 boiler rooms

FALI Job ID: 5151-6571

Date(s) Collected: 12/06/2010

Total Samples Submitted: 7

Total Samples Analyzed: 7

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
20101206-562-PLM-01	11058644						
Layer: Beige Plaster							ND
Layer: White Plaster							ND
Layer: Paint							ND
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
20101206-562-PLM-02	11058645						
Layer: Off-White Non-Fibrous Material							ND
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
20101206-562-PLM-03	11058646						
Layer: Yellow Fibrous Material							ND
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace) Fibrous Glass (95 %)							
20101206-562-PLM-04	11058647						
Layer: Beige Fibrous Material							ND
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace) Fibrous Glass (80 %)							
20101206-562-PLM-05	11058648						
Layer: Off-White Non-Fibrous Material							ND
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
20101206-562-PLM-06	11058649						
Layer: Grey Paint							ND
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
20101206-562-PLM-07	11058650						
Layer: Beige Plaster							ND
Layer: Off-White Plaster							ND
Layer: Paint							ND
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							

Client Name: U.C. Santa Barbara

Report Number: B142810

Date Printed: 12/08/10

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
-----------	------------	---------------	------------------	---------------	------------------	---------------	------------------



James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by Forensic Analytical Laboratories Inc. (FALI) at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by FALI to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by FALI. The client is solely responsible for the use and interpretation of test results and reports requested from FALI. Forensic Analytical Laboratories Inc. is not able to assess the degree of hazard resulting from materials analyzed. FALI reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.

University of California, Santa Barbara
 Environmental Health and Safety - Client # 5151
 Asbestos and Lead Program -- Contact J. Ripley 805-893-7984 jerome.ripley@dcs.ucsb.edu

Bulk Sample Log
 Asbestos

Project: Santa Rosa/Carrillo Dining Boiler Replacement Date: 12/06/2010 W.O.#: 292-62

Sampler Name: G. Horstin Building Name/Number: Bldgs. 527 & 562 boiler rooms

Sample Analysis	Turn Around		
PLM	12 HR	24 HR	Other
Lab Instructions:	Due Date: 12/08/2010		

Sample No.	Material(s)	HIDING	Location
20101206-562-PLM-01	White stucco, plaster.		Bldg. 562, boiler room, south wall.
20101206-562-PLM-02	White debris.		Bldg. 562, boiler room, on 12" run in middle of room.
20101206-562-PLM-03	Rope gasket.		Bldg. 562, boiler room, on boiler #1, north side of boiler.
20101206-562-PLM-04	Tank insulation.		Bldg. 562, boiler room, on boiler #2, on east side.
20101206-562-PLM-05	White debris.		Bldg. 562, boiler room, on top of 12" east/west run, middle of room.
20101206-562-PLM-06	Grey paint.		Bldg. 562, boiler room, floor, between boilers #1 & 2.
20101206-527-PLM-07	White plaster.		Bldg. 527, south boiler room, on beam on east side of room.

Chain of Custody

Relinquished by Name: G. Horstin Company: UCSB

Date/Time: for 4 hrs

Received by Name: Betty Fuchs Company: FASI

Date/Time: 12/7/10 11am

Digitally signed by G. Horstin
 DN: cn=G. Horstin, o=UCSB, ou=Design and Construction, email=g.horstin@dcs.ucsb.edu
 Reason: I am the issuer of this statement
 Date: 2010.12.06 14:22:00 -0800



Metals Analysis of Paints

U.C. Santa Barbara
Jerome Ripley
Design and Construction Svcs
Building 370
Santa Barbara, CA 93106

Client ID: 5151
Report Number: M115353
Date Received: 12/07/10
Date Analyzed: 12/09/10
Date Printed: 12/09/10
First Reported: 12/09/10

Job ID / Site: Santa Rosa/Carrillo Dining Boiler Replacement, Bldgs. 527 & 562 boiler rooms
Date(s) Collected: 12/06/10

FALI Job ID: 5151-6571
Total Samples Submitted: 3
Total Samples Analyzed: 3

Sample Number	Lab Number	Analyte	Result	Result Units	Reporting Limit*	Method Reference
20101206-562-PB-01	30389348	Pb	720	ppm	80	EPA 3050B/7420
20101206-562-PB-02	30389349	Pb	70	ppm	60	EPA 3050B/7420
20101206-562-PB-03	30389350	Pb	60	ppm	60	EPA 3050B/7420

* The Reporting Limit represents the lowest amount of analyte that the laboratory can confidently detect in the sample, and is not a regulatory level. The Units for the Reporting Limit are the same as the Units for the Final Results.

Dave Sandusky, CIH, Laboratory Supervisor, Hayward Laboratory

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. Any modifications that have been made to referenced test methods are documented in Forensic Analytical's Standard Operating Procedures Manual. Sample results have not been blank corrected. Quality control and sample receipt condition were acceptable unless otherwise noted.

Project: Santa Rosa/Carrillo Dining Boiler Replacement Date: 12/06/2010 W.O.#: 292-62

Sampler Name: G. Horstin Building Name/Number: Bldgs. 527 & 562 boiler rooms

Sample Analysis	Turn Around		
TTLc Pb	12 HR	24 HR	Other
Lab Instructions:	Due Date: <u>12/09/2010</u>		

Sample No.	Material(s)	HID No.	Location
20101206-562-Pb-01	Blue paint on metal substrate.		Bldg. 562, boiler room, on boiler #2.
20101206-562-Pb-02	Grey paint on concrete substrate.		Bldg. 562, boiler room, on floor east of boiler #1.
20101206-562-Pb-03	White paint on concrete substrate.		Bldg. 562, boiler room, on south wall.

Chain of Custody

Relinquished by Name: G. Horstin Company: UCSB

Received by Name: Betty Felt Company: FASI

Date/Time: 12/7/10
11:45 am

Digitally signed by Gene Horstin
 DN: cn=Gene Horstin, o=UCSB, ou=Design and Construction, email=horstin@dcs.ucsb.edu
 Reason: I am the author of this document
 Date: 2010.12.07 16:10:10 -0800