



Photograph 1. View north of the study area from El Colegio Road. Vegetation within the site is comprised of a mix of non-native species as well as native wetland and upland plants.



Photograph 2. View southwest of the swale constructed to accommodate flows from the culvert under El Colegio Road. Note the hydrophytic vegetation in the foreground and stand of willows in the background.



Photograph 3. View west of Sample Point 3. This area receives flows from two swale systems. Note the dense cover of *Distichlis spicata*.



Photograph 4. View west from the culvert located in the northeast portion of the parcel. *Typha latifolia* associated with the drainage can be seen in the foreground, with the depressional wetland dominated by *Scirpus* spp. and associated willow stands in the background.